
0058 Street Elbow, Elbow; hot dipped galvanized Inspection Process

- 1 .All photos with time watermark

2. Take photos of factory door.

3. When arrive the warehouse, check the Packing & Marking and take photos

4. Check the goods of each model according to PI.
 - 4.1 take detailed photos of each model of product.
 - 4.2 check the size of each model of product
 - 4.3 check the weight of each model of product

5. Test items
 - 5.1 Galvanizing thickness
 - 5.2 Surface quality – products are smooth, free from sand sticking, air holes, cracks and other defects
 - 5.3 Accuracy of thread
 - 5.4 Thread chamfering
 - 5.5 Leakage test

6. Factory could offer the test reports which they did in the third party laboratory.

Loading process

- 1- Before loading, take pictures of the empty container and take one with clear serial number of the container.



- 2- Take photos when loading



- 3- Seal the container.

